

CASE STUDY - WALTHAM CROSS LINE MARKING IN BASEMENT CARPARK

The managing agents of this property approached us to provide yellow line hatching as a parking measure in the under croft parking area due to ongoing issues with double parking and access to spaces for the residents.

We recommended the introduction of yellow line hatching using thermoplastic paint which has subsequently had the desired effect.

All products were thermoplastic applied products, melted onto the roadway with a crystal coat application to raise the visibility in headlights.

The result is a large reduction in parking in this area and safe access for property owners.

Target Maintenance GB Ltd were fully accredited throughout this works instruction. The accreditations include CHAS, Safecontractor and Constructionline.











